

# CASE HISTORY

Carlin Ranch  
Rock River, Wyoming



## 27 - Push Piers Driven to a depth of 33' below the basement

A cattle ranch located in Rock River, WY that was built in 1985 and has been settling since. This has developed into issues with opening doors and windows as well as various settling throughout the structure. Underground exploration revealed streams that caused issues with the soil beneath the home.



800-822-7437 | [www.magnumpiering.com](http://www.magnumpiering.com)

**MAGNUM**  
PIERING  
designed to support